



Photo 1 – View of damaged fuselage (Photo courtesy of the FAA)



Photo 2 – View of residual fuel in fuel tank (Photo courtesy of the FAA)