



Photo 1 – View of airplane in situ (Photo courtesy unknown)



Photo 2 – View of damaged fuselage from below (Photo courtesy of the FAA)



Photo 3 – View of damaged pilot side floorboards (Photo courtesy of the FAA)