



Photo 1 – View of fuselage damage (photo courtesy of the pilot)



Photo 2 - View of right wing damage (photo courtesy of the pilot)