



Photo 1 – View of right landing gear support damage (photo courtesy of the pilot)



Photo 2 - View of left landing gear support damage (photo courtesy of the pilot)