



Photo 1 – View of damaged airplane (photo courtesy of the FAA)



Photo 2 - View of aft fuselage damage (photo courtesy of the FAA)



Photo 3 - View of left wing damage (photo courtesy of the FAA)



Photo 4 - View of vertical stabilizer damage (photo courtesy of the FAA)