



**Photo 1 – View of right wing and fuselage damage (photo courtesy of the FAA)**



**Photo 2 - View of left wing damage (photo courtesy of the FAA)**