



Photo 1 – View of fuselage and vertical stabilizer damage (photo courtesy of the pilot)



Photo 2 - View of damage to both wings (photo courtesy of the pilot)