



**Photo 1 – View of airplane in situ (Photo courtesy unknown)**



**Photo 2 – View of left wing damage (Photo courtesy unknown)**