



**Photo 1 – View of left wing damage (photo courtesy of the FAA)**



**Photo 2 - View of right horizontal stabilizer damage (photo courtesy of the FAA)**