



Photo 1 – View of right front passenger door with emergency exit placard (Photo courtesy of the FAA)



Photo 2 – View of right rear passenger door latch in up/closed position (Photo courtesy of the FAA)



Photo 3 – View of fuselage damage on right side (Photo courtesy of the FAA)



Photo 4 – View of internal damage of fuselage on right side (Photo courtesy of the FAA)