



Photo 1 – View of airplane in grass adjacent to the runway (Photo courtesy of the FAA)



Photo 2 – View of damaged engine mounts (Photo courtesy of the FAA)