

Photo 1 – View of damaged left wing (courtesy of the FAA)



Photo 2 - View of damaged right wing (courtesy of the FAA)




Photo 3 – View of damaged fuselage (courtesy of the FAA)