



Photo 1 – View of damaged windshield from bird strike (courtesy of the FAA)



Photo 2 – View of damaged windshield from the pilot’s seat (courtesy of the FAA)