



Photo 1 – Airplane Impacted in the Snow as Viewed from Top (Photos 1 thru 13 Courtesy of Long B. Nguyen of Washington Air Search and Rescue-WSDOT)



Photo 2 – Accident Site with Helicopter Above



Photo 3 – Helicopter near Accident Site



Photo 4 – Helicopter Rescuing Pilots



Photo 5 – Helicopter Hovering above Accident Site



Photo 6 – Helicopter Accomplishing Rescue



Photo 7 - Helicopter Accomplishing Rescue



Photo 8 – Accident Site



Photo 9 – Accident Site



Photo 10 – Helicopter Accomplishing Rescue



Photo 11 – View of Airplane from the Rear



Photo 12 – Helicopter Hovering above Accident Site



Photo 13 – Airplane Wreckage as Viewed from the Top Left Side