

WPR20CA113 Accident Pictures:



Figure 1: Airplane at accident site (left side).



Figure 2: Airplane's damaged left wing (forward view).