



Photo 1 – Nosed over airplane with damaged vertical stabilizer (courtesy of online news outlet)



Photo 2 – Right side view of nosed over airplane (courtesy of the pilot)