



Photo 1 – View of accident airplane (Photo courtesy of Cirrus Aircraft)



Photo 2 – View of damaged lower fuselage (Photo courtesy of the FAA)



Photo 3 – View of disconnected fuel injector air reference line in engine compartment (Photo courtesy of Cirrus Aircraft)



Photo 4 – Closer view of disconnected air reference line in engine compartment (Photo courtesy of Cirrus Aircraft)