

Photo 1 – Diagram picture of the accident location (Photo courtesy of the FAA)




Photo 2 – Diagram picture of accident site (Photo courtesy of the FAA)



Photo 3 – View of accident airplane (Photo courtesy of the NTSB)



Top of Tree That Was Struck. Located
on Ground Approximately 10 Feet
From Aircraft Wreckage

Photo 4 – Photo of tree that was struck (Photo courtesy of the FAA)



Photo 5 – Wing damage from tree impact (Photo courtesy of the FAA)




Photo 6 – inReach tracker, last known ping of the airplane (Photo courtesy of Garmin)