

WPR20CA052 Accident Pictures.



Image 1: Right wing damage as viewed from bottom.



Image 2: Right wing damage as viewed from the right.