



Photo 1 – View of airplane inverted (Photo courtesy of the pilot)



Photo 2 – View of damaged left wing (Photo courtesy of the FAA)