

Photo 1 – View of accident airplane and damaged wings (Photo courtesy of the FAA)



Photo 2 - Rear view of accident airplane (Photo courtesy of the FAA)



Photo 3 – View of airplane trim at the accident site (Photo courtesy of the FAA)




Photo 4 - Weight and balance for accident flight submitted by CFI (Photo courtesy of the FAA)