



**Photo 1 – View of accident airplane inverted (Photo courtesy of the airport manager)**



**Photo 2 – View of damaged right wing lift strut (Photo courtesy of the airport manager)**