



**Photo 1 – View of left rear wing root (Photo courtesy of the operator)**



**Photo 2 – View of damaged left fuselage (Photo courtesy of the operator)**