

# **NATIONAL TRANSPORTATION SAFETY BOARD**

WASHINGTON, D.C.

CEN11MA258

Accident Report Photographs

(3 Pages)



**Photo 1 – Wreckage viewed from the airplane’s left side, viewer is looking east. (NTSB Photo)**



**Photo 2 – Wreckage viewed from the airplane’s right rear, viewer is looking northwest.  
(NTSB Photo)**