



Photograph 1 – Airplane – Aft View (provided by law enforcement)



Photograph 2 – Right Main Landing Gear (provided by FAA)



Photograph 3 – Lower right wing skin (provided by FAA)