



Photo 1 – Overview of Recovered Wreckage (Textron Photo)



Photo 2 - Overview of Recovered Wreckage (Textron Photo)



Photo 3 – Left and Right Wings



Photo 4 – Right Horizontal Stabilizer



Photo 5 – Right Horizontal Stabilizer



Photo 6 – Windshield Assembly



Photo 7 – Fuselage Section



Photo 8 – Fuselage Section



Photo 9 – Right Engine



Photo 10 – Right Engine



Photo 11 – Vertical Stabilizer / Rudder (Textron Photo)