



MU Accident - Incident Report

Date: 6-10-17 Train # 7623 East RSU # 7744 West RSU # 7695
Location: ML-3 Responding Employee: Vilca/Barrett/Turner

Type of Incident: (Check)
Trespasser Strike
Vehicle Strike
Other

LOG # 2283709

Description of Incident: Employee Strike

Weather Condition: Sunny Temp. 75°

SEALS		
Sealed	Yes	No
ATC	<input checked="" type="checkbox"/>	<input type="checkbox"/>
SSS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
ALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>
DR BY-PS	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Condition and Operation of the Following:

Components:	Operating	Defective
Head Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ditch Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Condition and Operation of the Following:

Components:	Operating	Defective	Comment on any Defect
Head Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Remark: <u>N/A</u>
Ditch Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Remark: <u>N/A</u>
Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Remark: <u>N/A</u>
Bell	<input type="checkbox"/>	<input type="checkbox"/>	Remark: <u>N/A</u>
Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Remark: <u>N/A</u>

Brake Cylinder Pressure Reading

CAR #	EMERGENCY	MIN BRAKE	MAX BRAKE
7695	50	12	45
7696	50	14	45
7403	48	13	43
7404	50	13	44
7417	49	13	44
7418	49	11	43
7625	49	14	44
7626	44	12	44
7049	48	14	44
7050	46	14	44
7743	50	13	43
7744	50	16	45

Supervisor: Vilca
IBM #: 28057

QMP: Barrett
IBM #: 52689

FAX COMPLETED FORM TO CENTRAL CONTROL 718-558-8015

Attached Form to Log Int: [REDACTED] CC Manager Approval: [REDACTED]