

Photo 1 – Wreckage from Right




Photo 2 – Wreckage from Front Left



Photo 3 – Damage to Propeller Blade



Photo 4 – Damage to Propeller Blade