



Photo 1 – View of the inverted main wreckage. Photo taken from nose looking aft toward tail.



Photo 2 – View of inverted main wreckage. Photo taken from end of right wing looking across wreckage toward left wing.



Photo 3 – View of inverted main wreckage. Photo taken from left side of tail looking forward toward nose of aircraft.



Photo 4 – Initial impact point at edge of culvert with main wreckage in background.