



**Photo 1 – Right side of helicopter showing damage.**



**Photo 2 – Right side of helicopter showing rotor blades and tie down rope wrapped around rotor assembly**



**Photo 3 – Close up of damage and rotor blade tie down rope wrapped around rotor assembly.**