

IANUFACTURER <u>CESSNA</u> EGISTRATION NUMBER <u>N-8145 M</u> NGINE(S) CURRENTLY INSTALLED. AFG <u>CONTINENTAL</u> MODEL <u>TO-470</u> PROPELLER(S) CURRENTLY INSTALLED. MFG <u>McCAuley</u> HUB MODEL <u>SERIAL (L) 6858</u> BLADE MODEL <u>S806F-0 (L) SERIAL (736121)</u> 5314	U
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---

NAME HENRE MONJAUZE	ADDRESS		
CITY SAN FRANCISCO			TO
NAME		, ,	
כוזץ	STATE	FROM	_ то
NAME	ADDRESS		
CITY	STATE	_ FROM	TO
NAME	ADDRESS		
CITY	STATE	_ FROM	
NAME	ADDRESS		
CITY	STATE	_ FROM	_ то
NAME			
כוזי	STATE	_ FROM	TO

	•			÷	
			•		

	1		

9	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
/16	1946.1			This aircraft has been inspected and
92.				determined to be in airworthy condition
				for a ferry Flight from San Francisco IA.P.
				Yo San CarTos Airport, CA. only. This flight
				1s for maintenance to aircraft.
				All A Rean
			· .	

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRI
2/16				THIS AIRCRAFT HAB BEEN INSPECTED
1993				AND DETERMINED TO BE IN AIRWOR
				CONDITION FOR A FERRY FLIGHT
				FROM SAN CARLOS, CA. TO HAYWARD
	1	· · ···		AIRPORT, CA. ONLY. THIS FLIGHT IS
<u> </u>				FOR MAINTENANCE TO AIRCRAFT.
		[
	-		†	INSPECTOR FAA APPROVED REPAIR STATION #BZV.R713C
	+		<u>†</u>	GOLDEN GATE AVIATION SAN CARLOS CALLE 94070
			<u> </u>	SAN CARLUS, CACIF. 94070
	_		 	
			ļ	

.

باللہ مرکب میں محمد میں ا

.

.

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
		· · · · · · · · · · · · · · · · · · ·		GERDES AVIATION SERVICES FAA Approved Repair Station G3RR399J The Altimeter/Static and Transponder Systems have been inspected to <u>/6,000</u> feet, and were found to comply with F.A.R. 43, Appendix E &F. N Number <u>8/45/4</u> Date <u>4-26,-02</u> Signature FAA APPROVED REPAIR STATION G3RR399J 4012 W. Commonwealth Ave. Fullerton CA 92833 Office (714) 525-7545
<u>. </u>			in i 2010 - Marine A	
		L		

DATE	RECORDING TACH	TODAYS	TOTAL TIME IN	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER
19	TIME	FLIGHT	SERVICE	MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTI
5-7-0	12/2052		Ž	Subul all control, Elean ful save
	'			clean repact Whee bearings - per
		gea	ret	action test Normal, check-EIT
		one	ratio	al funtion per FAR 91-207- DATTEXE
		Repl	ac!.	well selector placard w/New one
		Mar	K Luc	tron Gaap. Red leves . 3.8 - 5.9 Install
		mie	ing	screeks in instrument panel - serve
		bra	4.	enlace duct hose R/side enstament par
	-	10 cu	U.CA	trollcables under podertal
- <u></u>	1 7	Aml	he with	D # 72-14-08 EI Per AD. NEXt due 3152 OCI
			f. MUAL	
		Cels	V	OI M. Manual - Monte

. .

.

.

DAT	TACH	TODAYS	TOTAL TIME IN	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS
19	- TIME	FLIGHT	SERVICE	ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
				
				- ANNUALS ONLY
			_ <u></u>	5/1/01 HOBBS 1052 TTL 2052 TSMOH
				SEE AD LIST IN BACK OF AIRCRAFT LOG
				I CERTIFY THAT I HAVE INSPECTED THIS AIRCRAFT LOG ACCORDANCE WITH AN ANNUAL INSP. AND DETERMINED IT
				N SI45M ALEWORTHY
				R. L. JOHNSON IA
				AOCARD2JOB H;
· · · · ·				
	_1			