

**JACKSON HOLE AIRPORT FIELD
CONDITION & FRICTION MEASUREMENT
REPORT**

SARSYS SAAB FRICTION TESTER (SFH)

DATE: 11/22/2010

TIME: 9:20

FIELD CONDITIONS

RUNWAY 19		RUNWAY 01	
TOUCHDOWN =	40	TOUCHDOWN =	40
MID =	42	MID =	42
ROLLOUT =	40	ROLLOUT =	40
RUNWAY 01/19 CONDITON N.O.T.A.M.			
Patchy thin loose snow over patchy thin packed snow and ice.			
TAXIWAY N.O.T.A.M.			
Patchy thin loose snow over patchy thin packed snow and ice.			
TAXIWAY A MU:	A1 - A2 39	A2 - A3 31	A3 - A4 38
RAMP N.O.T.A.M.			
Patchy thin loose snow over patchy thin packed snow and ice.			
RAMP MU:	COMMERCIAL 21	GENERAL AVIATION 21	
COMMENTS			
Snow removal in progress.			
REPORTED TO:		LOCKHEED MARTIN, PRESCOTT HUB 1-877-4-US-NTMS	
FSS	<input checked="" type="checkbox"/>	INITIAL <u>AN</u>	TOWER <input checked="" type="checkbox"/>
JHAB	<input checked="" type="checkbox"/>	JHAV	<input checked="" type="checkbox"/>
WWFS	<input type="checkbox"/>	SWA <input checked="" type="checkbox"/>	UNITED <input checked="" type="checkbox"/>
NWA	<input type="checkbox"/>	LYNX	<input type="checkbox"/>

REPORTING OFFICER: P. Walters

TIME: 9:20

Original Date: _____

Revision Date: _____

FAA Approval: _____

