



Airworthiness - Photo 12. View of the left side of the aft cabin and tail section. Note the bowing deformation of the separated rudder (denoted by arrow) and the twisting of the vertical stabilizer toward the right side of the airplane. (NTSB-C7)