



Airworthiness - Photo 9. Close-up view of the leading edge skin of the left wing (view from forward looking aft). Note hydrodynamic deformation in aft direction. (NTSB-I12)