

CEN09PA348 Airworthiness Group Factual Report
Appendix 1
Figures

Agusta A-109E, N606SP




Figure 1 – Wreckage Disposition



Figure 2 –Fuselage

Agusta A-109E, N606SP



Figure 3 – Rotor Hub



Figure 4 – Main Rotor Blade Sections

Agusta A-109E, N606SP



Figure 5 – Tailboom



Figure 6 – Tail Rotor Blade A, Serial Number L70

Agusta A-109E, N606SP



Figure 7 – Tail Rotor Blade B, Serial Number L138



Figure 8 - Tail rotor skid tube.