

# INSPECTION RECORD

## F.A.R. 43.11-91.409

DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTION-STATUS&DISCREPENCY LIST-SIGNATURE -CERT.NO. OF APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE
5-Dec-18	HM 4243.9 TT: 6438.2	<p>Complied with 100/ annual IAW R22 MM 2.400 &amp; LOM. Replaced Spark plugs with New UREM 38S Fine wire per owner request, Check compration as follows: 1)75/80 2/76/80 3)77/80 4)74/80, Drain oil replanish with fresh 100 AW, replaced oil filter with New, Replaced mags with fresh Inspected repaired Mags SN C05192 &amp; E15CA157R SB-113A, ADSB compiance was done by tropic radio at this time See Radio checks page for log book entry with GTX 33ES transponder serial Number 89122476.</p> <p>Run helicopter check operation OK, I certify that this helicopters has been Inspected IAW R22MM 2.400, Lom and CFR43 Appx D for 100 Hours /Annual and has been found to be airworthy at this time, All AD's noted to been complied with to this date</p> <p style="text-align: center;">[REDACTED]</p> <p>Elfas Dakak</p> <p>A&amp;P [REDACTED]</p>

21/03/2019 09:36