



**Photo 1 – Balloon After Landing**



**Photo 2 – Balloon with Basket Tipping Forward**



**Photo 3 – Accident Site**



**Photo 4 – Balloon Basket and Burners**



**Photo 5 – Balloon Burner System**

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6/10/18			37.85	<b>ANNUAL INSPECTION</b> - I certify that this aircraft (N711FN s/n 1117) has been inspected per checklist of Kubicek Balloons and all annual inspection requirements met and this aircraft is determined to be in airworthy condition with <b>37.85</b> logged hours. Tested Burners, Fuel Hoses and Tanks for function and leaks per mfg specs.. There are no AD's applicable to this aircraft as of this time. Details of the complete annual inspection can be found on Work Order <b>3050</b> dated <b>June 10, 2018</b> Repairman No. & Name [REDACTED]
6/10/18			37.85	CRS: [REDACTED] Falcon's Nest Repair Station Cortland, OH 44410
6/10/18				Install K13 s/n 743 basket and remove K17. Replace Ignis burner with Ignis s/n 1495 & 1496. Remove tanks and replaced with Kuhnigh tanks s/n 3150/84 & [REDACTED]
6/10/18				
6/28/18	.60		38.45	Asklund Balloon Chest - Media Flight
6/28/18	.75		39.20	" " " - Balloon Chest
6/29/18	.80		40.00	" " " - Media Flight

Photo 6 – Balloon Annual Inspection