Factual Report – Attachment 1

Images from the Merrill Pass Low, Beluga and Nikiski FAA weather cameras for the times surrounding the accident period.

METEOROLOGY

ANC17FA049

The Merrill Pass Low camera was located about 37 miles west of the accident location at an elevation of 3,045 feet at coordinates: 61.2°, -153.2978°.

The Beluga cameras were located about 29 miles west of the accident location at an elevation of 75 feet at coordinates: 61.185493°, -151.034566°.

The Nikiski camera was located about 36 miles west of the accident location at an elevation of 301 feet at coordinates: 60.77879°, -151.129229°.




Figure A – Diagram depicting the views for the Merrill Pass Low FAA weather cameras.




Figure B – Clear day image for the southeast-facing Merrill Pass Low FAA weather camera.



Figure C – Southeast-facing Merrill Pass Low camera image at about 2220 AKDT.



Figure D – Southeast-facing Merrill Pass Low camera image at about 2230 AKDT.




Figure E – Southeast-facing Merrill Pass Low camera image at about 2240 AKDT.




Figure F – Southeast-facing Merrill Pass Low camera image at about 2250 AKDT.




Figure G – Diagram depicting the views for the Beluga FAA weather cameras.






Figure I – Northwest-facing Beluga camera image at about 2213 AKDT.



Figure J – Northwest-facing Beluga camera image at about 2223 AKDT.



Figure K – Northwest-facing Beluga camera image at about 2233 AKDT.



Figure L – Northwest-facing Beluga camera image at about 2243 AKDT.



Figure M – Clear day image for the southwest-facing Beluga FAA weather camera.



Figure N – Southwest-facing Beluga camera image at about 2220 AKDT.




Figure O – Southwest-facing Beluga camera image at about 2230 AKDT.




Figure P – Southwest-facing Beluga camera image at about 2240 AKDT.




Figure Q – Diagram depicting the views for the Nikiski FAA weather cameras.



Figure R – Clear day image for the northwest-facing Nikiski FAA weather camera.



Figure S – Northwest-facing Beluga camera image at about 2209 AKDT.



Figure T – Northwest-facing Nikiski camera image at about 2220 AKDT.



Figure U – Northwest-facing Nikiski camera image at about 2229 AKDT.



Figure V – Northwest-facing Nikiski camera image at about 2239 AKDT.

Submitted by: Mike Richards NTSB, AS-30