



Pedestrian SIR-Highway Accident Brief


Attachment 1-1: MTA Investigator Scene Diagram

Manhattan, New York #2

HWY17SH006

(3 pages)

Date 10/21/16 Time 1745 Hours Route 907 Run 913 Operator/ Empl. Wickert, R Pass/PR# B00604 Bus/Veh. # 3190
Destination 188st & 64 Ave SLD/Manager 0017 Pass/PR# B00604




Supervisor's Accident/Crime Investigation Report

ACCIDENT DIAGRAM

(scale 1" = 20')

House # Number

Date 10/21/16 Time 1:50 Hours Route PM 7 Run 913 Operator/ Empl. Weekworth R Pass/PR# 3190
 Destination 188 St & 64 Ave SLD/Manager Ortiz Pass/PR# 37496



Supervisor's Accident/Crime Investigation Report

ACCIDENT DIAGRAM

(scale 1" = 20')