



1 2

SUBSTATION B-29, BREAKER 2S




Image of the Relay Oscillography of Substation B-29, Breaker 2S, Showing Electricity Draw and Spike over Time

Time, S

Vertical

Volts(Amps)/Div

Ch2

VA/Div

2000

Offset

-1939

- | | | | |
|---|--------------------------------|------------------------------|------------------------------|
| <input checked="" type="radio"/> Ch1 1000 | <input type="radio"/> Ch5 5000 | <input type="radio"/> Ch9 0 | <input type="radio"/> Ch13 0 |
| <input checked="" type="radio"/> Ch2 2000 | <input type="radio"/> Ch6 5000 | <input type="radio"/> Ch10 0 | <input type="radio"/> Ch14 0 |
| <input type="radio"/> Ch3 5000 | <input type="radio"/> Ch7 0 | <input type="radio"/> Ch11 0 | <input type="radio"/> Ch15 0 |
| <input type="radio"/> Ch4 5000 | <input type="radio"/> Ch8 0 | <input type="radio"/> Ch12 0 | <input type="radio"/> Ch16 0 |

Horizontal

10 S/Div

-220.5 Offset(S)