

HOLLAND TRACK TESTING SERVICES - RED DEFECTS REPORT

Vehicle: TrackSTAR 484 Direction: S Units: MILES 06/01/2012 09:18am Page 2

Client: CONRAIL H#: 0002 Div: SOUTH JERSEY Sub: 9909 VINELAND SE RR Person: MIKE DIARENZO Trk Info: 9909 VIN

Def # Worst Loc. (MP) TRACK INFO R/Y Defect Max(in) Len(ft) Cls Safe (MPH) LM+FT Gage Latitude Longitude Crv

 MP 0008+4012 End of Territory Defect Grouping Summary for ALL Tracks

DEFECTS	RED	YEL	(REPEAT)
GAGE	1	20	
SURFACE	0	0	
ALIGNMENT	0	0	
UNBALANCE	0	0	
OTHER	0	0	
Total	1	20	

HOLLAND TRACK TESTING SERVICES - DEFECTS SUMMARY REPORT

Vehicle: TrackSTAR 484 Direction: S Units: MILES 06/01/2012 09:18am Page 1

Client: CONRAIL H#: 0002 Div: SOUTH JERSEY Sub: 9909 VINELAND SE RR Person: MIKE DIARENZO Trk Info: 9909 VIN

Def #	Worst Loc (MP)	TRACK INFO	R/Y Defect	Max(in)	Len(ft)	Cls	Safe(MPH)	LM+FT	Gage	Latitude	Longitude	Crv
0003	1.394(2079)	M:0	(SIMN) Y LGAGE_WIDE	1.37	0006	2		BR + 46	+1.05	039.93288	075.11074	C
0004	1.394(2082)	M:0	(SIMN) Y GAGE_WIDE	1.17	0012	2		BR + 48	+1.17	039.93288	075.11074	C
0005	1.427(2255)	M:0	(SIMN) Y GAGE_WIDE	1.20	0027	2		BR + 38	+1.20	039.93240	075.11077	S
0006	1.468(2471)	M:0	(SIMN) Y LGAGE_WIDE	1.31	0004	2		BR + 182	+0.98	039.93187	075.11089	C
0007	1.469(2475)	M:0	(SIMN) Y GAGE_WIDE	1.00	0003	2		BR + 185	+1.00	039.93187	075.11089	C
0008	1.475(2506)	M:0	(SIMN) Y LGAGE_WIDE	1.33	0007	2		BR + 219	+1.05	039.93176	075.11092	C
0009	1.475(2509)	M:0	(SIMN) Y GAGE_WIDE	1.13	0016	2		BR + 224	+1.13	039.93176	075.11092	C
0010	1.485(2562)	M:0	(SIMN) Y GAGE_WIDE	1.14	0010	2		BR + 40	+1.14	039.93160	075.11098	C
0011	1.509(2689)	M:0	(SIMN) Y GAGE_WIDE	1.03	0005	2		BR + 77	+1.03	039.93129	075.11114	C
0012	1.513(2709)	M:0	(SIMN) Y LGAGE_WIDE	1.28	0004	2		BR + 95	+1.10	039.93124	075.11116	C
0013	1.513(2710)	M:0	(SIMN) Y GAGE_WIDE	1.11	0015	2		BR + 101	+1.11	039.93124	075.11116	C
0014	1.517(2730)	M:0	(SIMN) Y LGAGE_WIDE	1.26	0003	2		BR + 117	+0.96	039.93120	075.11119	C
0015	1.520(2743)	M:0	(SIMN) Y GAGE_WIDE	1.02	0007	2		BR + 130	+1.02	039.93116	075.11121	C
0016	1.526(2778)	M:0	(SIMN) Y GAGE_WIDE	1.13	0015	2		BR + 171	+1.13	039.93107	075.11126	S
0017	1.542(2863)	M:0	(SIMN) Y LGAGE_WIDE	1.42	0023	2		BR + 50	+1.13	039.93087	075.11140	C
0018	1.543(2864)	M:0	(SIMN) Y GAGE_WIDE	1.18	0032	2		BR + 55	+1.18	039.93087	075.11140	C
0019	1.548(2891)	M:0	(SIMN) Y GAGE_WIDE	1.09	0011	2		BR + 63	+1.09	039.93083	075.11143	S
0020	1.560(2955)	M:0	(SIMN) Y LGAGE_WIDE	1.33	0010	2		BR + 126	+1.13	039.93067	075.11156	S
0021	1.561(2959)	M:0	(SIMN) Y GAGE_WIDE	1.19	0021	2		BR + 141	+1.19	039.93067	075.11156	S
0025	2.413(2179)	M:0	(SIMN) Y GAGE_WIDE	1.00	0004	2		CR + 75	+1.00	039.91877	075.11717	S
0029	8.738(3897)	M:0	(SIMN) R GAGE_WIDE	1.77	0006	2	-E--	SG + 234	+1.77	039.83322	075.15133	C

HOLLAND TRACK TESTING SERVICES - RED DEFECTS REPORT

Vehicle: TrackSTAR 484 Direction: S Units: MILES 06/01/2012 10:52am Page 1

Client: CONRAIL H#: 0003 Div: SOUTH JERSEY Sub: 9912 PENNSGROVE RR Person: MIKE DIARENZO Trk Info: 9912 PEN

Def # Worst Loc. (MP) TRACK INFO R/Y Defect Max(in) Len(ft) Cls Safe (MPH) LM+FT Gage Latitude Longitude Crv

 POST 0015+0312 End of Territory Defect Parameter Summary for ALL Tracks

DEFECT	RED	YEL	DEFECT	RED	YEL
GAGE	000	005	XLEVEL	000	000
SURFACE	000	000	REVERSE_XLV	000	000
DIP31	000	000	JOINT	000	000
SUPER_XLV	000	000	UNBALANCE	000	000
TWIST	000	000	ALIGN62	000	000
WARP62	000	000	TANK_CAR	000	000
OVERELEV	000	000	HARM_XLV	000	000
CANT	000	000	HIGH_ROAD	000	000
	RED	YEL			
Total	000	005			

HOLLAND TRACK TESTING SERVICES - DEFECTS SUMMARY REPORT

Vehicle: TrackSTAR 484 Direction: S Units: MILES 06/01/2012 10:52am Page 1

Client: CONRAIL H#: 0003 Div: SOUTH JERSEY Sub: 9912 PENNSGROVE RR Person: MIKE DIARENZO Trk Info: 9912 PEN

Def #	Worst Loc. (MP)	TRACK INFO	R/Y Defect	Max(in)	Len(ft)	Cls	Safe (MPH)	LM+FT	Gage	Latitude	Longitude	Crv
0038	8.932(4921)	M:0	(SIMN) Y GAGE_WIDE	1.10	0043	2		FR + 102	+1.10	039.83149	075.15202	S
0039	8.955(5040)	M:0	(SIMN) Y LGAGE_WIDE	1.27	0006	2		FR + 182	+1.10	039.83121	075.15219	C
0040	8.955(5042)	M:0	(SIMN) Y GAGE_WIDE	1.11	0011	2		FR + 184	+1.11	039.83121	075.15219	C
0041	8.961(5074)	M:0	(SIMN) Y GAGE_WIDE	1.12	0017	2		FR + 227	+1.12	039.83112	075.15226	C
0047	13.991(5232)	M:0	(SIMN) Y GAGE_WIDE	1.20	0011	2		RX + 22	+1.20	039.83456	075.24136	S

HOLLAND TRACK TESTING SERVICES - RED DEFECTS REPORT

Vehicle: TrackSTAR 484 Direction: S Units: MILES 06/01/2012 11:25am Page 2

Client: CONRAIL H#: 0004 Div: SOUTH JERSEY Sub: 9912 PAULSBORO S RR Person: MIKE DIARENZO Trk Info: 9912 PAU

Def # Worst Loc.(MP) TRACK INFO R/Y Defect Max(in) Len(ft) Cls Safe(MPH) LM+FT Gage Latitude Longitude Crv

MP 0015+0163 End of Territory Defect Grouping Summary for ALL Tracks

DEFECTS	RED	YEL	(REPEAT)
GAGE	3	4	
SURFACE	1	0	
ALIGNMENT	0	0	
UNBALANCE	0	0	
OTHER	0	0	
Total	4	4	

HOLLAND TRACK TESTING SERVICES - DEFECTS SUMMARY REPORT

Vehicle: TrackSTAR 484 Direction: S Units: MILES 06/01/2012 11:25am Page 1

Client: CONRAIL H#: 0004 Div: SOUTH JERSEY Sub: 9912 PAULSBORO S RR Person: MIKE DIARENZO Trk Info: 9912 PAU

Def #	Worst Loc. (MP)	TRACK INFO	R/Y Defect	Max(in)	Len(ft)	Cls	Safe(MPH)	LM+FT	Gage	Latitude	Longitude	Crv
0048	14.030(0159)	5:9912 (SIDE)	R GAGE_TGHT	-1.16	0019	1	-E--	FR + 15	-1.16	039.83456	075.24319	S
0049	14.046(0244)	5:9912 (SIDE)	R GAGE_TGHT	-1.21	0022	1	-E--	SW + 22	-1.21	039.83458	075.24349	S
0050	14.076(0402)	5:9912 (SIDE)	R GAGE_TGHT	-0.60	0015	1	-E--	SW + 180	-0.60	039.83457	075.24404	S
0051	14.107(0567)	5:9912 (SIDE)	Y GAGE_WIDE	1.37	0010	1		SW + 340	+1.37	039.83454	075.24461	S
0052	14.107(0565)	5:9912 (SIDE)	Y LGAGE_WIDE	1.74	0014	1		SW + 340	+1.32	039.83454	075.24461	S
0053	14.111(0585)	5:9912 (SIDE)	Y GAGE_WIDE	1.33	0007	1		SW + 359	+1.33	039.83454	075.24470	S
0054	14.130(0688)	5:9912 (SIDE)	Y LGAGE_WIDE	1.56	0021	1		FR + 16	-0.73	039.83450	075.24504	C
0055	14.225(1188)	5:9912 (SIDE)	R WARP62.62	-3.57	0011	1	-E--	FR + 47	-0.18	039.83417	075.24675	S

HOLLAND TRACK TESTING SERVICES - RED DEFECTS REPORT

Vehicle: TrackSTAR 484 Direction: S Units: MILES 06/01/2012 01:04pm Page 1

Client: CONRAIL H#: 0005 Div: SOUTH JERSEY Sub: 9912 PENNSGROVE RR Person: MIKE DIARENZO Trk Info: 99122 PE

Def # Worst Loc.(MP) TRACK INFO R/Y Defect Max(in) Len(ft) Cls Safe(MPH) LM+FT Gage Latitude Longitude Crv

 POST 0031+0227 End of Territory Defect Parameter Summary for ALL Tracks

DEFECT	RED	YEL	DEFECT	RED	YEL
GAGE	000	007	XLEVEL	000	000
SURFACE	000	000	REVERSE_XLV	000	000
DIP31	000	000	JOINT	000	000
SUPER_XLV	000	000	UNBALANCE	000	002
TWIST	000	000	ALIGN62	000	000
WARP62	000	001	TANK_CAR	000	000
OVERELEV	000	000	HARM_XLV	000	000
CANT	000	000	HIGH_ROAD	000	000

RED YEL

Total 000 010

HOLLAND TRACK TESTING SERVICES - DEFECTS SUMMARY REPORT

Vehicle: TrackSTAR 484 Direction: S Units: MILES 06/01/2012 01:04pm Page 1

Client: CONRAIL H#: 0005 Div: SOUTH JERSEY Sub: 9912 PENNSGROVE RR Person: MIKE DIARENZO Trk Info: 99122 PE

Def #	Worst Loc. (MP)	TRACK INFO	R/Y Defect	Max(in)	Len(ft)	Cls	Safe (MPH)	LM+FT	Gage	Latitude	Longitude	Crv
0058	14.472(2493)	M:0	(SIMN) Y WARP62:26	-1.78	0004	3		FR + 6	+0.27	039.83279	075.25185	T
0064	16.828(4371)	M:0	(SIMN) Y GAGE_WIDE	1.06	0006	3		CR + 266	+1.06	039.82664	075.29403	S
0065	16.847(4469)	M:0	(SIMN) Y GAGE_WIDE	1.02	0015	3		CR + 364	+1.02	039.82659	075.29439	C
0066	16.862(4549)	M:0	(SIMN) Y GAGE_WIDE	1.06	0009	3		CR + 444	+1.06	039.82654	075.29461	C
0067	16.865(4568)	M:0	(SIMN) Y LGAGE_WIDE	1.30	0004	3		CR + 460	+0.90	039.82653	075.29469	C
0068	16.851(4491)	M:0	(SIMN) Y VMAX 3IN	2.22	0184	3		CR + 475	+0.83	039.82657	075.29446	C
0069	16.943(4979)	M:0	(SIMN) Y VMAX 3IN	2.23	0343	3		SW + 287	+0.56	039.82607	075.29601	C
0076	29.087(0461)	M:0	(SIMN) Y LGAGE_WIDE	1.25	0015	2		RX + 45	+0.22	039.72462	075.47417	S
0077	29.380(2006)	M:0	(SIMN) Y GAGE_WIDE	1.08	0007	2		RX + 58	+1.08	039.72056	075.47356	C
0078	29.898(4741)	M:0	(SIMN) Y LGAGE_WIDE	1.30	0004	2		CR + 426	+0.78	039.71376	075.47688	C

HOLLAND TRACK TESTING SERVICES - RED DEFECTS REPORT

Vehicle: TrackSTAR 484 Direction: S Units: MILES 06/01/2012 03:11pm Page 1

Client: CONRAIL H#: 0006 Div: SOUTH JERSEY Sub: 9913 DEEPWATER I RR Person: MIKE DIARENZO Trk Info: 9913 DEE

Def # Worst Loc.(MP) TRACK INFO R/Y Defect Max(in) Len(ft) Cls Safe(MPH) LM+FT Gage Latitude Longitude Crv

 POST 0033+5133 End of Territory Defect Parameter Summary for ALL Tracks

DEFECT	RED	YEL	DEFECT	RED	YEL
GAGE	000	001	XLEVEL	000	000
SURFACE	000	000	REVERSE_XLV	000	000
DIP31	000	000	JOINT	000	000
SUPER_XLV	000	000	UNBALANCE	000	000
TWIST	000	000	ALIGN62	000	000
WARP62	000	000	TANK_CAR	000	000
OVERELEV	000	000	HARM_XLV	000	000
CANT	000	000	HIGH_ROAD	000	000
	RED	YEL			
Total	000	001			
