



Highway Accident Brief: Pedestrian SIR

Scene Photographs

Bronx, New York

HWY17SH004

(7 pages)



Photo #1: View of the eastbound approached to intersection from parking lane.



Photo #2: View of eastbound approached to intersection from point right lane becomes a travel lane.



Photo #3: Closer view of eastbound approach and pedestrian crosswalk.



Photo #4: Intersection of West Fordham Road and Sedgwick Avenue, showing south side pedestrian crosswalk.



Photo #5: Close-up view of southside crosswalk, looking eastbound.



Photo #6: Pedestrian view looking westbound at southside crosswalk and pedestrian control signal device.



Photo #7: Exemplar bus traveling southbound at the intersection of West Fordham Road and Sedgwick Avenue.




Photo #8: Close-up view looking westbound at the southside crosswalk and the right eastbound turning lane from West Fordham Road onto Sedgwick Avenue.



Photo # 9: From the southwest corner of West Fordham Road looking south on Sedgwick Avenue.



Photo #10: Photograph of crash school bus parked at bus depot.



Photo #11: Photograph of exemplar school bus returning to depot.