



- 3/31/15 2300 Carman Eskew reports for duty at the Carmen's Office
- 3/31/15 2300 Y39131 reports for duty at the Yard Office
- 3/31/15 2317 Y39131 completes required safety tests and sweeps zone prior to making N09 solid
- 3/31/15 2310 Q40130 arrives on #2 Main and sets 87 cars to N02. Q40130 picks up N06
- 4/1/15 0039 Yardmaster briefs with Carman Eskew and turns over N04 with 63 cars
- 4/1/15 0115 Yardmaster briefs with Carman Eskew and turns over N02 with 87 cars
- 4/1/15 0134 Q40130 doubles N06 to their train on #3 Main
- 4/1/15 0134 After Q40130 exits zone, Y39131 sweeps zone
- 4/1/15 0231 Yardmaster briefs with Carman Eskew for a roll by inspection on 17 cars for Q03201
- 4/1/15 0233 Y39131 lines route after Q40130 clears and starts to move toward N01
- 4/1/15 0251 Y39131 pulls North out of N01 and strikes Carman Eskew at the N02 switch