

# Safety RAR - Railroad Accident Reporting

Incident Number: R000167264 Incident Date/Time: 03/07/2017 15:11

## Summary

Is this the first striking consist: No

Train ID:	Q60607	Non Train Desc:	Non Train Code:		
Accident Type:	Hwy-rail crossing	FRA Reportable:	No	Equipment Damage:	\$1,000.00
Equipment Type:	Freight train			Engineering Damage:	\$1,000.00
				Foreign Damage:	\$0.00

## Consist Details

Trailing Tons:	3990	Remote Loco Operation:	Not a remotely controlled operation	TimeTable Directions:	North
Speed:	19	Speed Estimate/Record:	Recorded	Authorized Speed:	45
Train Length:	3163	Transporting Passengers:	N	Auth. Speed Perm/Temp:	Permanent

### Number of:

Passenger	Loaded:	0	Derailed Loaded:	0	Empty:	0	Derailed Empty:	0
Freight	Loaded:	27	Derailed Loaded:	0	Empty:	25	Derailed Empty:	0
Crude oil	Carrying:	000	Derailed:	000	Leaking:	000		
Carbooses			Derailed:					
Hazmat	Carrying:	26	Derailed:	0	Leaking:	0	Amt Released:	Unit of Measure:

Hazmat STCC Commodity List:

Total Cars:52 Total Derailed:0

## Track Details

Track Name: SINGLE MAIN	Main Track Obstructed time: 5 Hrs 37 Mins	FRA Track Class: Freight speed 60, passenger speed 80
-------------------------	---	---

### Equipment Territory:

Track Type: Main	Method of Auth: SIGNALLED INDICATION
Track Subtype: R-Main - primary	Supp Code Pos 3:
Track Density:	Supp Code Pos 4:
Signalization: SIGNALLED	Supp Code Pos 5:

Rail Type: Continuous Welded Rail

Method of Operation:

## First Involved Equipment

Initial: CSXT	Number: 230	Position: 1	AAR Car Type: D127	
Loaded: Yes	Weight(tons):	End of Equip Derailed:	First Wheel Derailed:	Wheel Actions:
Special Track Feature: Rail-highway grade crossing		Distance from point of derailment to rest(ft):		

## Causing Equipment

Is this equipment same as the First involved?: Yes

**Initial:** CSXT **Number:** 230 **Position:** 1 **AAR Car Type:** D127  
**Loaded:** Yes **Weight(tons):** **End of Equip Derailed:** **First Wheel Derailed:** **Wheel Actions:**

**Special Track Feature:** Rail-highway grade crossing **Distance from point of derailment to rest(ft):**

## Locomotives

**Distributed Power:** No

Initial	Number	Order in Train	Position	Derailed	LDVR	ERAD
CSXT	230	1	Head	No	Yes	Yes
CSXT	7870	2	Head	No	Yes	Yes
CSXT	7805	3	Head	No	Yes	Yes

## Crew

**Equipment Attended:** Yes

Employee Id	Position	On Duty(Hrs,Min)	Consec Days Worked	Prior Hours Off	Tox Test
227535	Conductor	6 Hrs,41 Mins	2	14	No
378283	Engineer	6 Hrs,41 Mins	2	14	No

## Remarks

**Remarks:**

TRAIN STRUCK BUS AT MP000626.6 MAIN ST. IN BILOXI MS. BUS WAS STUCK ON THE TRACKS.. AGE UNKNOWN. . AGE UNKNOWN.

**Reported by:** 03/07/2017 21:39 **Status:** Not Started  
**Last update:** C9642 03/09/2017 10:46