Row	Department	Subdepartment	Railroad	Type	Subtype	Assessment	Rules	Craft	Employee Status	Employee	Date	Time	Duration	Trainer	Train ID	Main Assessor	Assisting	CIP	Discipline	Loc./MP	End Loc./MP	Comments
1	Transcoastion		DSNO	EFFICIENCY		6.0 Reverse Movements	6.0 Reverse Movements - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/16/2018	16:10:00			M101	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
2	Transcoastion		DSNO	EFFICIENCY		6.32 Road Crossings	6.32 Road Crossings - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/16/2018	16:10:00			M101	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
3	Transcoastion		DSNO	EFFICIENCY		7.1.1 Position of Switches & Derails (Doublechecks)	7.1.1 Position of Switches & Derails (Doublechecks) - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/16/2018	16:10:00			M101	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
4	Transcoastion		DSNO	EFFICIENCY		7.4 Hand Brake Releases	7.4 Hand Brake Releases - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/16/2018	16:10:00			M101	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
5	Transcoastion		DSNO	EFFICIENCY		7.9 Securing Equipment	7.9 Securing Equipment - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/16/2018	16:10:00			M101	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
6	Transcoastion		DSNO	EFFICIENCY		7.1.2 Safety Steps	7.1.2 Safety Steps - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/16/2018	16:10:00			M101	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
7	Transcoastion		DSNO	EFFICIENCY		7.12 Movements into Sour Tracks	7.12 Movements into Sour Tracks - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/16/2018	16:10:00			M101	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
8	Transcoastion		DSNO	EFFICIENCY		8.1 Switches Hand Operation of Switches	8.1 Switches Hand Operation of Switches - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/16/2018	16:10:00			M101	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
9	Transcoastion		DSNO	EFFICIENCY		7.2 Communication Between Crews Switchlist	7.2 Communication Between Crews Switchlist - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/16/2018	01:00:00			Multiple	Brian Buttenwieth	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		The DTBS crew stopped half the range of vision on sort-up due test
10	Transcoastion		DSNO	EFFICIENCY		6.28 Movement on Other Than Main Track	6.28 Movement on Other Than Main Track - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/19/2018	20:05:00			DTBS	Brian Buttenwieth	C			DSNO: Wildwood Industrial: Wildwood / MP 630 7		
11	Transcoastion		DSNO	EFFICIENCY		6.28 Movement on Other Than Main Track	6.28 Movement on Other Than Main Track - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/19/2018	15:30:00			O-708	Joe Newsom	C			DSNO: Garland: Garland / MP 751		
12	Transcoastion		DSNO	EFFICIENCY		8.9 Restrictive Switch to Normal Position	8.9 Restrictive Switch to Normal Position - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/19/2018	15:30:00			O-708	Joe Newsom	C			DSNO: Garland: Garland / MP 751		
13	Transcoastion		DSNO	EFFICIENCY		Getting On/Off Equipment	Getting On/Off Equipment - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/19/2018	15:30:00			O-708	Joe Newsom	C			DSNO: Garland: Garland / MP 751		
14	Transcoastion		DSNO	EFFICIENCY		Job Briefing	Job Briefing - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/19/2018	15:30:00			O-708	Joe Newsom	C			DSNO: Garland: Garland / MP 751		
15	Transcoastion		DSNO	EFFICIENCY		Main Track Authority	6.10 Yard Limits - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/19/2018	15:30:00			O-708	Joe Newsom	C			DSNO: Garland: Garland / MP 751		
16	Transcoastion		DSNO	EFFICIENCY		Other Safety Rules	Other Safety Rules - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	01/19/2018	15:30:00			O-708	Joe Newsom	C			DSNO: Garland: Garland / MP 751		Had weekly safety rule filled out and complete Everything was done properly, safety inspection, air break test.
17	Transcoastion		SETUP			US Part 232 Air Brake - Field Eval - Set-up		US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	02/28/2018	15:00:00			O-7016	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
18	Transcoastion		DSNO	EFFICIENCY		6.28 Movement on Other Than Main Track	6.28 Movement on Other Than Main Track - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	02/28/2018	16:02:00			O-7016	Michael Stewart	C			DSNO: West Dallas: West Dallas / MP 0.3		
19	Transcoastion		DSNO	EFFICIENCY		7.1.1 Position of Switches & Derails (Doublechecks)	7.1.1 Position of Switches & Derails (Doublechecks) - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	02/28/2018	16:02:00			O-7016	Michael Stewart	C			DSNO: West Dallas: West Dallas / MP 0.3		
20	Transcoastion		DSNO	EFFICIENCY		7.4 Hand Brake Releases	7.4 Hand Brake Releases - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	02/28/2018	16:02:00			O-7016	Michael Stewart	C			DSNO: West Dallas: West Dallas / MP 0.3		
21	Transcoastion		DSNO	EFFICIENCY		7.9 Securing Equipment	7.9 Securing Equipment - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	02/28/2018	16:02:00			O-7016	Michael Stewart	C			DSNO: West Dallas: West Dallas / MP 0.3		
22	Transcoastion		DSNO	EFFICIENCY		"7 Step Protection" Compliance	"7 Step Protection" Compliance - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	02/28/2018	16:02:00			O-7016	Michael Stewart	C			DSNO: West Dallas: West Dallas / MP 0.3		
23	Transcoastion		DSNO	EFFICIENCY		Assaulted/Retreated Handbrakes	Assaulted/Retreated Handbrakes - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	02/28/2018	16:02:00			O-7016	Michael Stewart	C			DSNO: West Dallas: West Dallas / MP 0.3		
24	Transcoastion		DSNO	EFFICIENCY		Transfer Train Air Test	Transfer Train Air Test - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	02/28/2018	16:02:00			O-7016	Michael Stewart	C			DSNO: West Dallas: West Dallas / MP 0.3		
25	Transcoastion		DSNO	EFFICIENCY		218 ¶ 203 Efficiency Equipment on the Place	7.1.1 Position of Switches & Derails (Doublechecks) - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	03/28/2018	16:05:00			O-7016	Michael Stewart	C			DSNO: West Dallas: West Dallas / MP 0.3		Train was left in the clear not fouling cross over switch or any other track
26	Transcoastion		DSNO	EFFICIENCY		7.1.1 Position of Switches & Derails (Doublechecks)	7.1.1 Position of Switches & Derails (Doublechecks) - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	05/08/2018	22:20:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		
27	Transcoastion		DSNO	EFFICIENCY		"7 Step Protection" Compliance	"7 Step Protection" Compliance - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	05/08/2018	22:20:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		
28	Transcoastion		DSNO	EFFICIENCY		Getting On/Off Equipment	Getting On/Off Equipment - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	05/08/2018	22:20:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		
29	Transcoastion		DSNO	EFFICIENCY		218 ¶ 203 205-Hand-operated Main Track Switches	8.2 Position of Switches - Completed & 9 Main Track Switch - Completed & 8.0 Long Main Track Switch - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	05/08/2018	22:20:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		
30	Transcoastion		DSNO	EFFICIENCY		218 ¶ 203 209-Hand-operated Fixed Derails	8.20 Derail Location and Position - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	05/08/2018	22:20:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		
31	Transcoastion		DSNO	EFFICIENCY		802 (1) Track not fouled without proper protection. Working limits in place where track fouled with equipment	802 (1) Track not fouled without proper protection. Working limits in place where track fouled with equipment - Completed				05/17/2018	15:15:00				William Stowe	Mathew Cardelchet	C			DSNO: West Dallas: West Dallas		
32	Transcoastion		DSNO	EFFICIENCY		PPE	PPE - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	05/17/2018	15:15:00				William Stowe	Mathew Cardelchet	C			DSNO: West Dallas: West Dallas		
33	Transcoastion		DSNO	EFFICIENCY		218 ¶ 203 205-Hand-operated Main Track Switches	8.2 Position of Switches - Completed & 9 Main Track Switch - Completed & 8.0 Long Main Track Switch - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	06/10/2018	00:32:00			R-713	Michael Stewart	C			DSNO: Lewisville Industrial: Lewisville / MP 731		
34	Transcoastion		DSNO	EFFICIENCY		218 ¶ 203 209-Hand-operated Fixed Derails	8.20 Derail Location and Position - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	06/10/2018	00:32:00			R-713	Michael Stewart	C			DSNO: Lewisville Industrial: Lewisville / MP 731		
35	Transcoastion		DSNO	EFFICIENCY		218 ¶ 203 99-Reverse or Pushrod Movements	6.9 Reverse Movements - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	06/10/2018	00:32:00			R-713	Michael Stewart	C			DSNO: Lewisville Industrial: Lewisville / MP 731		
36	Transcoastion		DSNO	EFFICIENCY		6.32 Road Crossings	6.32 Road Crossings - Failed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	06/28/2018	19:00:00			O-7016	Michael Grier	F			DSNO: Carrollton: Carrollton / MP 603		left crossing blocked coached and counseled
37	Transcoastion		DSNO	EFFICIENCY		218 ¶ 203 209-Hand-operated Fixed Derails	8.20 Derail Location and Position - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	07/20/2018	02:10:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		
38	Transcoastion		DSNO	EFFICIENCY		218 ¶ 203 99-Reverse or Pushrod Movements	6.9 Reverse Movements - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	07/20/2018	02:10:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		
39	Transcoastion		DSNO	EFFICIENCY		5.9 Headlight Display	5.9 Headlight Display - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	07/20/2018	02:10:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		
40	Transcoastion		DSNO	EFFICIENCY		6.32 Road Crossings	6.32 Road Crossings - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	07/20/2018	02:10:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		
41	Transcoastion		DSNO	EFFICIENCY		7.1.1 Position of Switches & Derails (Doublechecks)	7.1.1 Position of Switches & Derails (Doublechecks) - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	07/20/2018	02:10:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		Was riding the rear car through the gates. I coached him on the rules of movement through gates and more though they are secure that he still needs to be on the ground when this movement is made
42	Transcoastion		DSNO	EFFICIENCY		7.10 Movement Through Gates or Doorways	7.10 Movement Through Gates or Doorways - Failed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	07/20/2018	02:10:00			R-713	Michael Stewart	F			DSNO: East Dallas: East Dallas / MP 210.3		
43	Transcoastion		DSNO	EFFICIENCY		8.1 Switches Hand Operation of Switches	8.1 Switches Hand Operation of Switches - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	07/20/2018	02:10:00			R-713	Michael Stewart	C			DSNO: East Dallas: East Dallas / MP 210.3		
44	Transcoastion		DSNO	EFFICIENCY		Assaulted/Retreated Handbrakes	Assaulted/Retreated Handbrakes - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	07/20/2018	18:27:00			R-713	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
45	Transcoastion		DSNO	EFFICIENCY		Getting On/Off Equipment	Getting On/Off Equipment - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	07/20/2018	18:27:00			R-713	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		
46	Transcoastion		DSNO	EFFICIENCY		Transfer Train Air Test	Transfer Train Air Test - Completed	US/Train/FRA Conductor	ACTIVE	Arauzamaa, Julio (Transcoastion)	07/20/2018	18:27:00			R-713	Michael Stewart	C			DSNO: Mesquite Yard: Mesquite Yard / MP 638		