

# COX AIRPARTS, LLC

## TEAR DOWN REPORT

CUSTOMER NAME & ADDRESS:

Power Packs Plus

DATE:

2/14/14

ATTENTION:

Ryan

DESCRIPTION:

Power Pack

PO#

9021

PART NUMBER:

31800-2

SERIAL #:

4455

DATE RECEIVED AT COX AIRPARTS:

2/18/14

SPECIAL INSTRUCTIONS FROM CUSTOMER:

Bench test. Teardown +

Overhaul.

TEST RESULTS, IF PERFORMED, PRIOR TO DISASSEMBLY OR REPAIR:

by Reservoir

Pressure bypassed

OBVIOUS PROBLEMS NOTED DURING TEAR DOWN:

Need to replace Pin 31822-00

Reservoir is over pressurized

REASSEMBLY PROCEDURE:

DA PA-27

Parts And Service Manual

TEST RESULTS FOLLOWING REPAIR OR OVERHAUL:

u

11

WORK ORDER #:

14-0047

INSPECTOR:

NUMBER: