



Exhibit 48-Photo Showing Rear Section of Center Sill Severed, Bent and Twisted on HZGX-150 Clip Car