



Exhibit 49- Photo Showing Rear End Section of Center Sill Crushed, Twisted and Buckled on HZGX-150 Clip Car