


Exhibit 15.

Site Map Documentation of the Wreckage Distribution

(map document is provided on the following page¹⁵²)

¹⁵² a larger, full-size version of this map, as compiled by the Track Working Group, is available in the NTSB public docket



#	ITEM	DESCRIPTION	STATUS	NOTES
U1	UP END	ON ZEE - DELETED	SEARCH LOCUMOTIVE	
U2	UP END	ON ZEE - (P-4.0)	SEARCH LOCUMOTIVE	
U3	UP END	ON ZEE - (P-4.0)	SEARCH LOCUMOTIVE	
U4	UP END	ON ZEE - (P-4.0)		
U5	UP END	ON ZEE - (P-4.0)		
U6	UP END	ON ZEE - (P-4.0)		
U7	UP END	ON ZEE - (P-4.0)		
U8	UP END	ON ZEE - (P-4.0)		
U9	UP END	ON ZEE - (P-4.0)		
U10	UP END	ON ZEE - (P-4.0)		
U11	UP END	ON ZEE - (P-4.0)		
U12	UP END	ON ZEE - (P-4.0)		
U13	UP END	ON ZEE - (P-4.0)		
U14	UP END	ON ZEE - (P-4.0)		

NOTES:
 1. All sketches contained in this report are to the north end of the main track unless otherwise noted.
 2. Notations on the location sketches are as follows:
 (P-4.0) = 4 feet from the end of the main track
 (P-4.0) = 4 feet from the end of the main track

WRECKAGE DISTRIBUTION DETAIL
 0 20 40
 0 20 40

NTSB REF NO. DCA-08-MR-009 ACCIDENT DATE 09/12/2008	METROLINK COMPUTER RAIL SYSTEM CHATSWORTH INCIDENT - MP 44.4.12 VENTURA SUBDIVISION	TRACK NO. 5 SCALE AS NOTED
DATE OF DRAWING 09/12/2008 DRAWN BY S. J. SMITH CHECKED BY S. J. SMITH SCALE 1" = 40'	ACCIDENT SITE MAP WRECKAGE DISTRIBUTION DETAIL	

-- End of Exhibit --