

METROLINK DELAY REPORT

TRAIN# 111

LAUS TO MPK

	TIME		TIME
ON DUTY	2:00 PM	DP LAUS	3:35
AR GDL	3:45	DP GDL	3:45
AR BUR	3:51	DP BUR	3:51
AR BBA	3:55	DP BBA	3:55
AR VNC	4:02	DP VNC	4:02
AR NTH	4:14	DP NTH	4:14
AR CWT	4:20	DP CWT	4:20
AR SIM		DP SIM	
AR MPK		OFF DUTY	TO #118

CREW CONSIST DATA	
DATE:	09-12-08
ENG. NO.:	855
CAB CAR NO.:	617
NO. OF CARS:	617, 207, 185
ENGR:	R. M. SANCHEZ
COND:	RK. HELDENBERG
PAX COUNT:	268
PEAK PAX COUNT:	189
Bikes #	13 Peak 11 Turned Away 0
MAP FORM COMPLETED:	YES <input type="radio"/> NO <input checked="" type="radio"/>
MAP CODES:	0
LOST & FOUND ITEM DESCRIPTION:	0
ITEM'S DISPOSITION:	0

FARE COMPLIANCE

No. Paxes Check:	Verbals 640B1:	Verify Team Names:	0
Written Warning:	0	640B2:	Sheriff Team Names: 0
Citations:	0	640B11:	Access: 1 R2R: 1
CAR 1 2 3 4 5 6	LEVEL <input checked="" type="radio"/> UP <input checked="" type="radio"/> LOWER	LOCATION OF CHECK:	BUR-VNC

FIRST CAR BEHIND LOCO IS No.1,

LOCATION BETWEEN WHAT STATIONS

CALCULATION OF TIME LOST

SEGMENT	MINS	ACT	LOST	SEGMENT	MINS	ACT	LOST
LAUS GDL	10	10	0	NTH CWT	7	6	0
GDL BUR	6	6	0	CWT SIM	12		
BUR BBA	4	4	0	SIM MPK	17		
BBA VNC	7	7	0				
VNC NTH	7	12	5				

EXPLANATION OF DELAYS (SHOW IN GEOGRAPHIC ORDER)

CODE	MINS	LOCATION	REASON
	5	VNC-NTH	WAIT @ CP RAYMER FOR AMTK 789